COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : **1120**

Date : _____

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer
B.B.M.P Bangalore
Yelahanka Sub Division
Bangalore - 64

2. Well Location : 2nd Nitte Meenakshi College BSF compus

3. Total Well Depth / Drilled in Ft. : 1130 ft

4. Casing Erected in Ft. : 240 ft

5. Water Struck at the Depth of : 380

6. Total Yield (Measuring method "V" Norch : 2.5" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 390 & 180'

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

AE-I

Asst. Executive Engineer
Yelahanka Sub Division
(BBMP Yelahanka Zone)
Yelahanka, Bangalore

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Smt. Kavitha Singh

Water Diviner

COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1119 Date : _____

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Old Town

2. Well Location : 1st main, 26th cross, Vidya Nagar

3. Total Well Depth / Drilled in Ft. : 1130 ft

4. Casing Erected in Ft. : 200 ft

5. Water Struck at the Depth of : 300

6. Total Yield (Measuring method "V" Norch : 2.5 / / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 390 & 780

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

AE-1

Asst. Executive Engineer
Yelahanka Sub Division
(BBMP Ynk. Zn.)
Yelahanka, Bangalore

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Smt. Kavitha Singh

Water Diviner